



FEMALE L.V. SOCKET RETAINER ASSEMBLY 45-1A18

NOTE:

**ITEMS NOT SOLD
SEPARATELY.
ITEM 101.1 IS SOLD
AS A COMPLETE
ASSEMBLY**



The Female L.V. Retainer Socket Assembly is a replacement to the Standard L.V. Assembly. The configuration for this particular L.V. Socket Assembly, is such that the L.V. cable may now be removed from the hose bundle without removing the Robot Side Base Plate or cutting the L.V. Cable.

Figure 24.1

DESCRIPTION	ITEM #	FIG	EFC PART #	SAMES® PART #
FEMALE L.V. RETAINER ASS'Y	101.1	24.1	45-1A18	N/A